

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## **IMAGES ARE BEST AVAILABLE COPY.**

As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.




FIG. 2




FIG. 1

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




Fig. 3

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




Fig. 5




Fig. 4

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




FIG. 7





FIG. 6

FIG. 8



TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




FIG. 9

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




FIG. 10

10. [COUPLING CLAMP TO HOSE]
11. [PROVIDING CLAMP INSERT DEVICE]
12. [PROVIDING OPEN CHANNEL IN DEVICE TO STRAPDLE HOSE]  
14. [ASSEMBLING IDENTIFICATION PLATE WITH CROSS MEMBER]
16. [PROVIDING ENGRAVING MEMBER ON DEVICE TO SECURE DEVICE TO HOSE CLAMP]
18. [SELECTIVELY ATTACHING DEVICE TO CLAMP]
20. [MARKING DEVICE TO IDENTIFY THOSE CONTENTS]

FIG. 11